



Hubshell

100

110

A NDS Flange \varnothing

47mm

47mm

B NDS Center to Flange

24mm

29mm

C DS Center to Flange

37mm

42mm

D DS Flange \varnothing

42mm

42mm

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing