



Hubshell
100

A NDS Flange \varnothing
40mm

B NDS Center to Flange
23mm

C DS Center to Flange
37mm

D DS Flange \varnothing
38mm

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing